

Product Safety Information

Box-type workbench Schäfer Shop Select PW 200-4, beech multiplex board or medium density fiberboard, up to 750 kg, W 2000 mm, choice of colors

Manufacturer/Responsible Person: Schäfer Shop GmbH, Industriestraße 65, 57518 Betzdorf, Deutschland
E-Mail: info@schaefer-shop.de

Please note the technical data of the products!

Article Numbers: 439809, 439807, 439806, 439805, 439802, 439801, 439569, 439567, 439566, 439565, 439562, 439561, 439329, 439327, 439326, 439325, 439322, 439321, 440049, 440047, 440046, 440045, 440042, 440041

Safety Instructions:

- Maximum load capacity: Do not exceed 750 kg. When using the workbench, take care not to overload it in order to avoid structural damage or accidents.
- The drawers may be loaded with a maximum of 80 kg. Overloading can damage the mechanism.
- Each shelf in the substructure has a maximum load capacity of 50 kg. Take care not to exceed this limit to avoid stability problems.
- Ensure stability: The workbench must stand on a stable and level floor and be correctly anchored to prevent tipping or wobbling.
- Children must not use the workbench, it is not suitable for use by children - take safety precautions when children are present.
- Wear suitable personal protective equipment such as gloves and safety goggles when working at the workbench to avoid injury.
- The workbench should only be used in dry indoor areas to avoid damage caused by moisture. Avoid contact with water and damp conditions, especially on the wooden surface.
- Only use the workbench for its intended purpose to avoid injury and product damage.
- Close drawers and doors properly to avoid the risk of crushing or accidents caused by falling objects.
- The ESD-conductive design protects electrical components - only use ESD-safe tools and observe the recommended ESD precautions to prevent damage.
- Read the assembly instructions before starting and check all parts. If the workbench or components are damaged, an inspection and, if necessary, a recall is required.
- Handle mechanical objects with sharp edges with care to avoid injury. Keep sharp or heavy objects away from the edges of the worktop.
- Regularly check the electrical components and accessories for damage to avoid the risk of electric shock.