

Product Safety Information

Longitudinal bracing, L 995 mm

Please note the technical data of the products!

Article Number: 31308

Safety Instructions:

- Ensure that the frame spacing for double shelving is at least 30 mm in order to guarantee subsequent height adjustability.
- The shelves must each be fitted with two longitudinal braces to ensure stability.
- Appropriate measures must be taken to ensure that only compliant and safe products are provided.
- Importers must provide clear instructions and safety information in a language that consumers can understand, unless the product can be used safely without this information.
- The storage or transport conditions must not affect the conformity of the product with the general safety requirement.