

Product Safety Information

Longitudinal bracing, L 1283 mm

Please note the technical data of the products!

Article Number: 31309

Safety Instructions:

- The frame spacing for double shelving must be at least 30 mm to ensure subsequent height adjustability.
- When using the product, the lower and upper shelves in each bay must be fitted with 2 longitudinal braces to ensure the required bay load-bearing capacity.
- It must be ensured that the products comply with the general safety requirements in order to guarantee the stability of the shelving system.
- Instructions for safe installation and use of the product must be included.
- The use of the product must not lead to dangerous situations, especially with regard to the tipping over or collapse of shelves.