

Product Safety Information

Cloakroom locker Evolo S 3000, steel, w. feet, 2 compartments w. each W 400 mm, security twist lock/cylinder lock, various colours

Manufacturer/Responsible Person: C+P Möbelsysteme GmbH & Co. KG, Boxbachstraße 1, 35236 Breidenbach, Deutschland
E-Mail: info@cp.de

Please note the technical data of the products!

Article Numbers: 402007, 402006, 402004, 402003, 402002, 402000, 401999, 401997, 401996, 401995

Safety Instructions:

- Make sure that the locker is on a stable, level surface and securely fastened to the wall to prevent it from tipping over.
- Avoid overloading the locker, observe the maximum load capacity of the shelves and ensure that no heavy objects are stored above the compartments to avoid injury.
- Check the function of the locks and hinges regularly and only use the recommended locks to ensure security and proper locking.
- During assembly, make sure that all parts are firmly and correctly installed to ensure stability.
- The locker is not suitable for use by children and should not be used as play equipment; supervise children to avoid injury.
- Only use the recommended cleaning methods to avoid damaging the coating of the locker and keep the locker away from sources of heat, water and moisture to prevent material deformation and corrosion.
- Watch out for sharp edges and avoid using or handling the locker with sharp objects to prevent injury.
- Secure personal items that are stored in accordance with existing safety regulations and ensure that the air passage is not blocked to ensure good ventilation.
- The plastic feet must be checked regularly for damage to prevent slipping movements and tipping over.
- Keep the ventilation openings free of blockages to ensure good air circulation.
- The doors of the locker must always be fully closed and locked to prevent unauthorised access and injury.
- Take care when handling heavy material to prevent back injuries.
- The use of unsuitable padlocks can compromise security; only use suitable locks.
- Avoid placing heavy and unstable objects on the top of the locker as this can cause it to tip over.