

Product Safety Information

Plate carriage with support surface on one side

Manufacturer/Responsible Person: Gabriel Transportsysteme GmbH, Frielinghausen 26, 59889 Eslohe, Deutschland

E-Mail: info@rollcart.de

Please note the technical data of the products!

Article Number: 91992

Safety Instructions:

- Take care when handling heavy panels: risk of injury due to incorrect lifting or moving.
- Do not use if damaged: Stability may be impaired if the wheels or frame are damaged.
- Check the fastenings and devices regularly for wear and damage.
- Ensure that the loading area is used properly: The product may become unstable if overloaded.
- Risk of injury: Keep hands and other parts of the body away from the cargo bed when moving the trolley.